



## 2009 TOYOTA HIACE COMMUTER 200 BUS

### Asset Details

<b>Build Date:</b>	6/2009
<b>Compliance:</b>	
<b>Make:</b>	TOYOTA
<b>Model:</b>	HIACE
<b>Variant:</b>	
<b>Series:</b>	COMMUTER 200
<b>Body Type:</b>	BUS
<b>Gearbox:</b>	4 SPEED
<b>Transmission:</b>	AUTOMATIC TRANSMISSION
<b>Engine Make:</b>	
<b>Engine Size:</b>	4 CYLINDER TURBO
<b>Fuel Type:</b>	DIESEL
<b>Diff Make / Size:</b>	
<b>Suspension:</b>	
<b>Ext Colour:</b>	WHITE DUCO
<b>Tyre Size:</b>	
<b>Tyre Condition:</b>	



<b>Doors:</b>	4	<b>Seats:</b>	14	<b>Length:</b>		<b>Capacity:</b>	
<b>Volume:</b>		<b>Height:</b>		<b>Width:</b>		<b>GVM:</b>	
<b>GCM:</b>		<b>SWL:</b>		<b>HP:</b>		<b>Tare:</b>	

### Asset Identification

<b>Odometer:</b>	704,945kms SHOWING	<b>Rego:</b>	S155 ADT	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JTFST22P600006625	<b>PIN:</b>					
<b>Engine No:</b>	1KD1931430	<b>Hours:</b>					
<b>Papers:</b>	YES	<b>Keys:</b>	1	<b>Books:</b>	NO	<b>Service Books:</b>	NO

### Features

AIR CON, CD PLAYER, BULL BAR, LWB  
AIR BAG  
POWER STEERING  
POWER WINDOWS

### Condition

Location	Damage
	DAMAGED FRONT BULL BAR
	MINOR SCRATCHES