

# 2006 TOYOTA HILUX KUN26R 150 SERIES DUAL CAB TRAY TOP 4x4

## Asset Details

<b>Build Date:</b>	8/2006
<b>Compliance:</b>	8/2006
<b>Make:</b>	TOYOTA
<b>Model:</b>	HILUX
<b>Variant:</b>	KUN26R
<b>Series:</b>	150 SERIES
<b>Body Type:</b>	DUAL CAB TRAY TOP
<b>Engine Size:</b>	3.0 LITRE
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	TURBO DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	BLACK/GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	4x4



## Asset Identification

<b>Odometer:</b>	235,637 Showing	<b>Rego:</b>	S134 BLZ	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	MR0FZ22G501002845			<b>PIN:</b>			
<b>Engine No:</b>				<b>Hours:</b>			
<b>Papers:</b>	NO	<b>Keys:</b>	2	<b>Books:</b>	NO	<b>Service Books:</b>	NO

## Features

AIR BAG, AIR CON, ALLOY TRAY, CD PLAYER, CENTRAL LOCKING, DECALS, IMMOBILISER, POWER STEERING, POWER WINDOWS, SIDE STEP, SPARE WHEEL, TOW BAR

## Tyres

<b>Front LHS:</b>	Poor	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------

## Condition

Location	Damage
FRONT GRILL/BUMPER	IMPACT DAMAGE/CRACKS
BATTERY	FLAT