



# 1999 TOYOTA LANDCRUISER HZ 75 BOOM SPRAY UTILITY 4x4

## Asset Details

|                      |                             |
|----------------------|-----------------------------|
| <b>Build Date:</b>   | 2/1999                      |
| <b>Compliance:</b>   | 3/1999                      |
| <b>Make:</b>         | TOYOTA                      |
| <b>Model:</b>        | LANDCRUISER                 |
| <b>Variant:</b>      | HZ                          |
| <b>Series:</b>       | 75                          |
| <b>Body Type:</b>    | BOOM SPRAY UTILITY          |
| <b>Engine Size:</b>  | 4 LITRE 6 CYLINDER          |
| <b>Transmission:</b> | 5 SPEED MANUAL TRANSMISSION |
| <b>Fuel Type:</b>    | DIESEL                      |
| <b>Ext. Colour:</b>  | WHITE DUCO                  |
| <b>Int. Colour:</b>  | GREY                        |
| <b>Doors:</b>        | 2                           |
| <b>Seats:</b>        | 3                           |
| <b>Drive Type:</b>   | 4x4                         |



## Asset Identification

|                   |                    |               |         |               |     |                       |     |
|-------------------|--------------------|---------------|---------|---------------|-----|-----------------------|-----|
| <b>Odometer:</b>  | 213,206kms SHOWING | <b>Rego:</b>  | WHD 146 | <b>State:</b> | SA  | <b>Expiry:</b>        |     |
| <b>VIN:</b>       | JT731PJ7508555628  | <b>PIN:</b>   |         |               |     |                       |     |
| <b>Engine No:</b> | 1HZ/1HZ0293545     | <b>Hours:</b> |         |               |     |                       |     |
| <b>Papers:</b>    | YES                | <b>Keys:</b>  | 1       | <b>Books:</b> | YES | <b>Service Books:</b> | YES |

## Features

FORWARD DUAL SPRAY BOOMS, OVERALL REACH 10m  
 1200 LITRE FIBREGLASS TANK  
 FOAM SPRAY  
 HARDI PILOT LCD IN CAB CONTROLS  
 HARDI & BERTOLINI PUMPS  
 HAND SPRAY REEL, STORAGE CAGE  
 ISOLATOR, REVERSE ALARM CAMERA

KEY #7

## Tyres

|                   |      |                   |      |                  |      |                  |      |               |      |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|
| <b>Front LHS:</b> | Poor | <b>Front RHS:</b> | Poor | <b>Rear LHS:</b> | Poor | <b>Rear RHS:</b> | Poor | <b>Spare:</b> | Poor |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|

## Condition

| Location | Damage                 |
|----------|------------------------|
|          | RADIATOR GRILL MISSING |
|          | DENTS & SCRATCHES      |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.