



# 1992 DAIHATSU ROCKY F77 SPRAY UTILITY 4x4

## Asset Details

<b>Build Date:</b>	7/1992
<b>Compliance:</b>	
<b>Make:</b>	DAIHATSU
<b>Model:</b>	ROCKY
<b>Variant:</b>	
<b>Series:</b>	F77
<b>Body Type:</b>	SPRAY UTILITY
<b>Engine Size:</b>	2.7 LITRE 4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	2
<b>Seats:</b>	2
<b>Drive Type:</b>	4x4



## Asset Identification

<b>Odometer:</b>	251,155km SHOWING	<b>Rego:</b>	NO REG	<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>	JDA000F7700004164	<b>PIN:</b>		<b>Hours:</b>			
<b>Engine No:</b>		<b>Books:</b>		<b>Service Books:</b>			
<b>Papers:</b>		<b>Keys:</b>	1				

## Features

AIR CON, ALLOY TRAY, SPARE WHEEL, TOOL BOX, TOW BAR, DUAL DRIVE CONTROLS  
 600 LITRE POLY TANK  
 4HP HONDA POWERED AR7C BP PUMP  
 2 x HAND SPRAY REELS  
 REVERSE CAMERA, ALL FAULTS,  
 DUAL KEY START LOCATION

KEY #5

## Tyres

<b>Front LHS:</b>	Good	<b>Front RHS:</b>	Good	<b>Rear LHS:</b>	Good	<b>Rear RHS:</b>	Good	<b>Spare:</b>	Good
-------------------	------	-------------------	------	------------------	------	------------------	------	---------------	------



## 1992 DAIHATSU ROCKY F77 SPRAY UTILITY 4x4

### Condition

Location	Damage
	DENT REAR DRIVER CORNER CAB
	DENT REAR PASSENGER TRAY
	MINOR DENTS & SCRAPES IN CAB & FRONT
	SECOND STEERING WHEEL MISSING