



# TCM FG18N18 FORKLIFT

## Asset Details

<b>Build Date:</b>							
<b>Make:</b>	TCM						
<b>Model:</b>	FG18N18						
<b>Series:</b>							
<b>Drive Type:</b>							
<b>Axle Config:</b>							
<b>Body Type:</b>	FORKLIFT						
<b>Gearbox:</b>							
<b>Transmission:</b>							
<b>Engine Make:</b>							
<b>Engine Size:</b>							
<b>Fuel Type:</b>	LPG/PETROL						
<b>Diff Make / Size:</b>							
<b>Suspension:</b>							
<b>Ext Colour:</b>							
<b>Tyre Size:</b>							
<b>Tyre Condition:</b>							
<b>Doors:</b>		<b>Seats:</b>		<b>Length:</b>		<b>Capacity:</b>	
<b>Volume:</b>		<b>Height:</b>		<b>Width:</b>		<b>GVM:</b>	
<b>GCM:</b>		<b>SWL:</b>		<b>HP:</b>		<b>Tare:</b>	



## Asset Identification

<b>Odometer:</b>		<b>Rego:</b>		<b>State:</b>		<b>Expiry:</b>	
<b>VIN:</b>				<b>PIN:</b>			
<b>Engine No:</b>				<b>Hours:</b>	12,320hours SHOWING		
<b>Papers:</b>		<b>Keys:</b>		<b>Books:</b>		<b>Service Books:</b>	

## Features

S/NO: 16L02799  
 SWL: 1,490kg  
 MAX LIFT: 4,350mm  
 3 STAGE CONTAINER MAST  
 SOLID TYRES  
 FIRE EXTINGUISHER

KEY #34

## Condition

<b>Location</b>	<b>Damage</b>
	SET DAMAGES, DENTS, SCRATCHES
	BROKEN PLASTICS

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.