




# 1991 MITSUBISHI PAJERO GLS STATION WAGON 4X4

## Asset Details

<b>Build Date:</b>	8/1991
<b>Compliance:</b>	
<b>Make:</b>	mitsubishi
<b>Model:</b>	PAJERO
<b>Variant:</b>	GLS
<b>Series:</b>	
<b>Body Type:</b>	STATION WAGON
<b>Engine Size:</b>	
<b>Transmission:</b>	5 SPEED MANUAL
<b>Fuel Type:</b>	DIESEL TURBO
<b>Ext. Colour:</b>	RED
<b>Int. Colour:</b>	
<b>Doors:</b>	5
<b>Seats:</b>	5
<b>Drive Type:</b>	4X4



## Asset Identification

<b>Odometer:</b>	475071	<b>Rego:</b>	S475AOW	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JMFNH7245MJ001727	<b>PIN:</b>					
<b>Engine No:</b>	HD56DV5154	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	NO

## Features

AIR CON, BULL BAR, CD PLAYER, SIDE STEP, SPARE WHEEL, SPOT LIGHTS, PAINT FADE OVERALL

## Tyres

<b>Front LHS:</b>	Average	<b>Front RHS:</b>	Average	<b>Rear LHS:</b>	Average	<b>Rear RHS:</b>	Average	<b>Spare:</b>	Poor
-------------------	---------	-------------------	---------	------------------	---------	------------------	---------	---------------	------

## Condition

Location	Damage
BACK DOOR	DENT
REAR RIGHT LIGHT COVER	BROKEN
REAR BUMPER	DENT
ROOF	SMALL DENTS
BULL BAR	DENT TO RIGHT SIDE