



# 2015 TOYOTA LANDCRUISER VDJ79R WORKMATE DUAL CAB TRAY UTILITY 4x4

## Asset Details

<b>Build Date:</b>	6/2015
<b>Compliance:</b>	7/2015
<b>Make:</b>	TOYOTA
<b>Model:</b>	LANDCRUISER
<b>Variant:</b>	VDJ79R
<b>Series:</b>	WORKMATE
<b>Body Type:</b>	DUAL CAB TRAY UTILITY
<b>Engine Size:</b>	4.5 LITRE V8
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	TURBO DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY/BROWN
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	4x4



## Asset Identification

<b>Odometer:</b>	73,315kms SHOWING	<b>Rego:</b>	S648 BHG	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	JTEBV71J004009084	<b>PIN:</b>					
<b>Engine No:</b>	1VD0297793	<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>		<b>Books:</b>	YES	<b>Service Books:</b>	YES

## Features

ABS, AIR BAG, AIR CON, BLUETOOTH, CD PLAYER, POWER STEERING, SIDE STEP, STEEL TRAY, TOOL BOX, TOW BAR, WARNING LIGHTS, MINE SPEC FIRE SUPPRESSION, ISOLATOR, SNORKEL, POLY TOOL BOX, POLY BULL BAR, LIGHT BAR, 3 x SUNRAYSIA RIMS, REAR LIGHTS

KEY #20

## Condition

Location	Damage
	RUST IN DOOR SEALS & AROUND WINDSCREEN
	DENTS & SCRATCHES, SURFACE RUST IN TRAY