

## TOYOTA HILUX SR 150 DUAL CAB TRAY UTILITY 4x4

### Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	11/2012
<b>Make:</b>	TOYOTA
<b>Model:</b>	HILUX
<b>Variant:</b>	SR
<b>Series:</b>	150
<b>Body Type:</b>	DUAL CAB TRAY UTILITY
<b>Engine Size:</b>	3 LITRE 4 CYLINDER
<b>Transmission:</b>	5 SPEED MANUAL TRANSMISISON
<b>Fuel Type:</b>	TURBO DIESEL
<b>Ext. Colour:</b>	WHITE DUCO
<b>Int. Colour:</b>	GREY
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	4x4



### Asset Identification

<b>Odometer:</b>	59,846kms SHOWING	<b>Rego:</b>	S239 AWN	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	MR0FZ22G101069135	<b>PIN:</b>					
<b>Engine No:</b>		<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>	1	<b>Books:</b>		<b>Service Books:</b>	

### Features

ABS, AIR BAG, AIR CON, BLUETOOTH, BULL BAR, CARGO BARRIER, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, SPARE WHEEL, STEEL TRAY, TOOL BOX, MINE SPEC SAFETY CELL, WORMALD FIRE SUPPRESSION, ISOLATOR, ANDERSON PLUG, SUNRAYSIA RIMS, CONTRACTOR ONE, 2 DRAWER TOOL BOX, GAS LIFT LID

KEY #17

### Condition

Location	Damage
	RUST EVIDENT IN DOOR SEALS & WINDSCREEN EDGE
	CRACK IN WINDSCREEN