



TCM FG18N18 FORKLIFT

Asset Details

Build Date:	
Make:	
Model:	
Series:	
Drive Type:	
Axle Config:	
Body Type:	
Gearbox:	
Transmission:	
Engine Make:	
Engine Size:	
Fuel Type:	
Diff Make / Size:	
Suspension:	
Ext Colour:	
Tyre Size:	
Tyre Condition:	



Doors:	Seats:	Length:	Capacity:
Volume:	Height:	Width:	GVM:
GCM:	SWL:	HP:	Tare:

Asset Identification

Odometer:	Rego:	State:	Expiry:
VIN:	PIN:		
Engine No:	Hours:		
Papers:	Keys:	Books:	Service Books:

Features

S/NO: 16L02799
 SWL: 1,490kg
 MAX LIFT: 4,350mm
 3 STAGE CONTAINER MAST
 SOLID TYRES
 FIRE EXTINGUISHER

KEY #34

Condition

Location	Damage
	SET DAMAGES, DENTS, SCRATCHES
	BROKEN PLASTICS

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.