



## 2006 HOLDEN COMMODORE EXECUTIVE SEDAN

### Asset Details

|                      |            |
|----------------------|------------|
| <b>Build Date:</b>   | 2006       |
| <b>Compliance:</b>   |            |
| <b>Make:</b>         | HOLDEN     |
| <b>Model:</b>        | COMMODORE  |
| <b>Variant:</b>      | EXECUTIVE  |
| <b>Series:</b>       |            |
| <b>Body Type:</b>    | SEDAN      |
| <b>Engine Size:</b>  | 6 CYLINDER |
| <b>Transmission:</b> | AUTO       |
| <b>Fuel Type:</b>    | PETROL     |
| <b>Ext. Colour:</b>  | WHITE      |
| <b>Int. Colour:</b>  | BLACK      |
| <b>Doors:</b>        | 4          |
| <b>Seats:</b>        | 5          |
| <b>Drive Type:</b>   |            |



### Asset Identification

|                   |                   |              |        |               |    |                       |            |
|-------------------|-------------------|--------------|--------|---------------|----|-----------------------|------------|
| <b>Odometer:</b>  | 160,958           | <b>Rego:</b> | XSH271 | <b>State:</b> | SA | <b>Expiry:</b>        | 31/01/2020 |
| <b>VIN:</b>       | 6GIZK52B56L849380 |              |        | <b>PIN:</b>   |    |                       |            |
| <b>Engine No:</b> | HBH061850246      |              |        | <b>Hours:</b> |    |                       |            |
| <b>Papers:</b>    | YES               | <b>Keys:</b> | 3      | <b>Books:</b> | NO | <b>Service Books:</b> | YES        |

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, SPARE WHEEL, TOW BAR

### Condition

| Location                    | Damage  |
|-----------------------------|---------|
| DRIVERS SIDE REAR BUMPER    | SCRAPED |
| DRIVERS SIDE REAR GUARD     | DENTED  |
| DRIVERS SIDE REAR DOOR      | SCRAPED |
| DRIVERS SIDE FRONT BUMPER   | SCRAPED |
| PASSENGER SIDE FRONT BUMPER | SCRAPED |
| PASSENGER REAR BUMPER       | CRACKED |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within.