

1999 NISSAN PULSAR N15 2 SEDAN

Asset Details

| | |
|----------------------|----------------|
| Build Date: | 5/1999 |
| Compliance: | |
| Make: | NISSAN |
| Model: | PULSAR |
| Variant: | N15 |
| Series: | 2 |
| Body Type: | SEDAN |
| Engine Size: | 4 CYLINDER |
| Transmission: | 5 SPEED MANUAL |
| Fuel Type: | UNLEADED |
| Ext. Colour: | MAROON |
| Int. Colour: | BLUE |
| Doors: | 4 |
| Seats: | 5 |
| Drive Type: | |



Asset Identification

| | | | | | | | |
|-------------------|-------------------|---------------|---------|---------------|-----|-----------------------|-----|
| Odometer: | 151467 | Rego: | S492ABS | State: | SA | Expiry: | |
| VIN: | JN1BCAN15A0538143 | PIN: | | | | | |
| Engine No: | GA16102666 | Hours: | | | | | |
| Papers: | YES | Keys: | 1 | Books: | YES | Service Books: | YES |

Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, POWER STEERING, SPARE WHEEL, DAMAGE TO ROOF WOULD CONSIDER THIS CAR A WRITE OFF

Tyres

| | | | | | | | | | |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|
| Front LHS: | Good | Front RHS: | Poor | Rear LHS: | Good | Rear RHS: | Poor | Spare: | Good |
|-------------------|------|-------------------|------|------------------|------|------------------|------|---------------|------|

Condition

| Location | Damage |
|--------------------------------|--------------------|
| DRIVERS SIDE TOP DOOR AND ROOF | DAMAGED/DENTED |
| BACK BUMPER | DENTED |
| FRONT BUMPER | SCRAPED BOTH SIDES |
| LEFT MIRROR | MISSING OUTER CASE |