

## MITSUBISHI EXPRESS L300 POP TOP CAMPER VAN

### Asset Details

<b>Build Date:</b>	
<b>Compliance:</b>	
<b>Make:</b>	MITSUBISHI
<b>Model:</b>	EXPRESS
<b>Variant:</b>	L300
<b>Series:</b>	
<b>Body Type:</b>	POP TOP CAMPER VAN
<b>Engine Size:</b>	4 CYLINDER
<b>Transmission:</b>	4 SPEED MANUAL TRANSMISSION
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	BEIGE
<b>Int. Colour:</b>	BEIGE/BROWNVINYL
<b>Doors:</b>	
<b>Seats:</b>	3
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	190,290kms SHOWING	<b>Rego:</b>	URL 067	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	SB3M38NH16003883	<b>PIN:</b>					
<b>Engine No:</b>	4632CJ8084	<b>Hours:</b>					
<b>Papers:</b>		<b>Keys:</b>	1	<b>Books:</b>		<b>Service Books:</b>	

### Features

TOW BAR, POOR CONDITION SUIT RESTORATION

KEY #54

### Condition

Location	Damage
ALUMINIUM BULL BAR	BROKEN
BODY	FADED PAINT/RUST
TAIL LIGHT	BROKEN