

## 2006 HOLDEN COMMODORE VE OMEGA SEDAN

### Asset Details

<b>Build Date:</b>	9/2006
<b>Compliance:</b>	
<b>Make:</b>	HOLDEN
<b>Model:</b>	COMMODORE
<b>Variant:</b>	VE
<b>Series:</b>	OMEGA
<b>Body Type:</b>	SEDAN
<b>Engine Size:</b>	6 CYLINDER
<b>Transmission:</b>	AUTOMATIC
<b>Fuel Type:</b>	PETROL
<b>Ext. Colour:</b>	WHITE
<b>Int. Colour:</b>	BLACK
<b>Doors:</b>	4
<b>Seats:</b>	5
<b>Drive Type:</b>	



### Asset Identification

<b>Odometer:</b>	180489	<b>Rego:</b>	S870AVS	<b>State:</b>	SA	<b>Expiry:</b>	
<b>VIN:</b>	6G1EK52B27L869747	<b>PIN:</b>					
<b>Engine No:</b>	LE0062480134	<b>Hours:</b>					
<b>Papers:</b>	NO	<b>Keys:</b>	1	<b>Books:</b>	YES	<b>Service Books:</b>	YES

### Features

AIR BAG, AIR CON, ALLOY WHEELS, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, POWER STEERING, POWER WINDOWS, SPARE WHEEL

### Condition

Location	Damage
FRONT BUMPER	CRACKED
EXTERIOR	MINOR DENTS & SCRATCHES
INTERIOR	HANDBRAKE & CENTRE CONSOLE DAMAGED
DRIVERS SEAT SURROUND	DAMAGED