



# 2010 TOYOTA LANDCRUISER GXL 150 SERIES STATION WAGON 4x4

### **Asset Details**

| Build Date:   | 2010                                |
|---------------|-------------------------------------|
| Compliance:   | 6/2010                              |
| Make:         | ΤΟΥΟΤΑ                              |
| Model:        | LANDCRUISER                         |
| Variant:      | GXL                                 |
| Series:       | 150 SERIES                          |
| Body Type:    | STATION WAGON                       |
| Engine Size:  | 4 CYLINDER, 3 LITRE<br>TURBO DIESEL |
| Transmission: | AUTOMATIC<br>TRANSMISSION           |
| Fuel Type:    |                                     |
| Ext. Colour:  | WHITE DUCO                          |
| Int. Colour:  | GREY                                |
| Doors:        | 4                                   |
| Seats:        | 7                                   |
| Drive Type:   | 4x4                                 |



## Asset Identification

| Odometer:  | 231,084kms<br>SHOWING | Rego: | S708 AHV | State: | SA | Expiry:        |  |
|------------|-----------------------|-------|----------|--------|----|----------------|--|
| VIN:       | JTEBH3FJ20K024691     |       |          | PIN:   |    |                |  |
| Engine No: |                       |       |          | Hours: |    |                |  |
| Papers:    |                       | Keys: | 1        | Books: |    | Service Books: |  |

#### **Features**

ABS, AIR BAG, AIR CON, BLUETOOTH, BULL BAR, CARGO BARRIER, CD PLAYER, CENTRAL LOCKING, CRUISE CONTROL, DECALS, FOG LAMPS, IMMOBILISER, POWER STEERING, POWER WINDOWS, SIDE STEP, SPOT LIGHTS, TRACTION CONTROL, DUAL BATTERIES BATTERY ISOLATION SWITCH DUAL SPARE WHEEL CARRIER

**KEY #7** 

## Condition

| Location | Damage                    |
|----------|---------------------------|
| ENGINE   | RUNS ROUGH & IS NOISY     |
|          | SUSPECTED INJECTOR FAILED |

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1