

# 1967 TOYOTA STOUT RK100 UTILITY/CAMPERVAN RWD

## Asset Details

|               |                             |
|---------------|-----------------------------|
| Build Date:   | 1967                        |
| Compliance:   |                             |
| Make:         | TOYOTA                      |
| Model:        | STOUT                       |
| Variant:      |                             |
| Series:       | RK100                       |
| Body Type:    | UTILITY/CAMPERVAN           |
| Engine Size:  | 1.9 LITRE                   |
| Transmission: | 4 SPEED MANUAL TRANSMISSION |
| Fuel Type:    | PETROL                      |
| Ext. Colour:  | WHITE DUCO                  |
| Int. Colour:  | BLUE                        |
| Doors:        | 2                           |
| Seats:        | 3                           |
| Drive Type:   | RWD                         |



## Asset Identification

|            |  |       |         |        |  |                |  |
|------------|--|-------|---------|--------|--|----------------|--|
| Odometer:  |  | Rego: | UFF 324 | State: |  | Expiry:        |  |
| VIN:       |  |       |         | PIN:   |  |                |  |
| Engine No: |  |       |         | Hours: |  |                |  |
| Papers:    |  | Keys: | 1       | Books: |  | Service Books: |  |

## Features

RARE TOYOTA STOUT UTE WITH A CAMPERVAN CONVERSION - RECOGNIZED IN SA REG AS A "CAMPERVAN" VEHICLE  
 WAS FOUND IN PT PIRIE & SAVED AFTER SITTING FOR APPROX 30 YEARS  
 ENGINE WILL RUN FOR SHORT PERIODS-WILL NEED FULL RESTORATION, IDEAL COFFEE TRUCK OR SIMILAR

## Tyres

|            |      |            |      |           |      |           |      |        |  |
|------------|------|------------|------|-----------|------|-----------|------|--------|--|
| Front LHS: | Poor | Front RHS: | Poor | Rear LHS: | Poor | Rear RHS: | Poor | Spare: |  |
|------------|------|------------|------|-----------|------|-----------|------|--------|--|

## Condition

| Location | Damage                               |
|----------|--------------------------------------|
|          | VEHICLE IS IN WEATHERED CONDITION    |
|          | FULL RESTORATION IS REQUIRED         |
|          | ENGINE TURNS OVER & RUNS MOMENTARILY |