



2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

Asset Details

Build Date:	2016		
Make:	VOLVO		
Model:	L120		
Series:			
Drive Type:			
Axle Config:			
Body Type:	WHEELED ARTICULATED FRONT END LOADER		
Gearbox:			
Transmission:			
Engine Make:	VOLVO		
Engine Size:	6 CYLINDER TURBO DIESEL		
Fuel Type:			
Diff Make / Size:			
Suspension:			
Ext Colour:			
Tyre Size:			
Tyre Condition:			
Doors:	Seats:	Length:	Capacity:
Volume:	Height:	Width:	GVM:
GCM:	SWL:	HP:	Tare:



Asset Identification

Odometer:	Rego:	State:	Expiry:
VIN:		PIN:	VCEL120FT00027711
Engine No:		Hours:	9,751hours SHOWING
Papers:	Keys:	Books:	Service Books:

Features

- 179kw (217HP)
- ENCLOSED A/C CAB
- ROPS/FOPS
- GP BUCKET 3.50m³
- LED FORWARD & REAR SPOTLIGHTS & WARNING BEACONS
- REAR CCTV & LCD SCREEN
- MINE SPEC FIRE SUPPRESSION SYSTEM
- BATTERY ISOLATION SWITCHES
- QMW INDUSTRIES WORK PLATFORM CONTROL SYSTEM
- EMERGENCY PUSH BUTTON STOP SWITCHES REAR & SIDE
- MISSING 1 x DOOR GLASS

KEY #58
ASSET #LS144



2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

Condition

Location	Damage
	MISSING 1 x DOOR GLASS