



## 2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

#### **Asset Details**

2016 **Build Date:** 

Make: **VOLVO** 

Model: L120

Series:

**Drive Type:** 

**Axle Config:** 

WHEELED ARTICULATED **Body Type:** FRONT END LOADER

Gearbox:

**Transmission:** 

**VOLVO Engine Make:** 

**6 CYLINDER TURBO Engine Size:** 

DIESEL

**Fuel Type:** 

Diff Make / Size:

Suspension:

**Ext Colour:** 

Tyre Size:

**Tyre Condition:** 







| Doors:  | Seats:  | Length: | Capacity: |
|---------|---------|---------|-----------|
| Volume: | Height: | Width:  | GVM:      |
| GCM:    | SWL:    | HP:     | Tare:     |

#### **Asset Identification**

| Odometer:  | Rego: | State: | Expiry:            |
|------------|-------|--------|--------------------|
| VIN:       |       | PIN:   | VCEL120FT00027711  |
| Engine No: |       | Hours: | 9,751hours SHOWING |
| Papers:    | Keys: | Books: | Service Books:     |

#### **Features**

179kw (217HP) ENCLOSED A/C CAB ROPS/FOPS GP BUCKET3.50m3 LED FORWARD & REAR SPOTLIGHTS & WARNING BEACONS REAR CCTV & LCD SCREEN MINE SPEC FIRE SUPPRESSION SYSTEM **BATTERY ISOLATION SWITCHES** QMW INDUSTRIES WORK PLATFORM CONTROL SYSTEM EMERGENCY PUSH BUTTON STOP SWITCHES REAR & SIDE MISSING 1 x DOOR GLASS

**KEY #58** ASSET #LS144





# 2016 VOLVO L120 WHEELED ARTICULATED FRONT END LOADER

### **Condition**

| Location | Damage                 |  |
|----------|------------------------|--|
|          | MISSING 1 x DOOR GLASS |  |