



## 1982 FORD CARGO 0913 MC4 4x2 SINGLE CAB TRAYTOP UTILITY

## **Asset Details**

| Build Date:       | 1982                          |
|-------------------|-------------------------------|
| Compliance:       | 1982                          |
| Make:             | FORD                          |
| Model:            | CARGO                         |
| Variant:          | 0913                          |
| Series:           | MC4                           |
| Body Type:        | SINGLE CAB TRAYTOP<br>UTILITY |
| Gearbox:          | 6 SPEED                       |
| Transmission:     | MANUAL TRANSMISSION           |
| Engine Make:      | FORD                          |
| Engine Size:      | 6 CYLINDER DIESEL             |
| Fuel Type:        |                               |
| Diff Make / Size: |                               |
| Suspension:       | SPRING SUSPENSION             |
| Ext Colour:       | RED DUCO                      |
| Tyre Size:        |                               |
| Tyre Condition:   |                               |
|                   |                               |







| Doors:  | 2        | Seats:  | 2 | Length: | Capacity: |         |
|---------|----------|---------|---|---------|-----------|---------|
| Volume: |          | Height: |   | Width:  | GVM:      | 9,000kg |
| GCM:    | 13,500kg | SWL:    |   | HP:     | Tare:     |         |

## **Asset Identification**

| Odometer:  | 187,806kms<br>SHOWING | Rego:    | VFW 102 | State: | SA | Expiry:        |
|------------|-----------------------|----------|---------|--------|----|----------------|
| VIN:       | CL4AAS8498            | 5G597154 |         | PIN:   |    |                |
| Engine No: |                       |          |         | Hours: |    |                |
| Papers:    |                       | Keys:    | 1       | Books: |    | Service Books: |

## **Features**

STEEL TRAY, ALLOY BULL BAR SPARE WHEEL LOAD BINDERS

KEY #42

This asset report has been based purely on an external walk around. There may be other damage, mechanical issues or body blemishes that are not contained within this report. It is the buyers responsibility to inspect the asset. The report is intended as a guide only and no guarantee or warranty whatsoever is made as to the accuracy of the information contained within. Page 1 of 1