



## 2016 HOLDEN CAPTIVA CG LTZ SUV STATION WAGON AWD

### Asset Details

|                      |                         |
|----------------------|-------------------------|
| <b>Build Date:</b>   | 2016                    |
| <b>Compliance:</b>   | 2016                    |
| <b>Make:</b>         | HOLDEN                  |
| <b>Model:</b>        | CAPTIVA CG              |
| <b>Variant:</b>      | LTZ                     |
| <b>Series:</b>       |                         |
| <b>Body Type:</b>    | SUV STATION WAGON       |
| <b>Engine Size:</b>  | 4 CYLINDER TURBO DIESEL |
| <b>Transmission:</b> | AUTOMATIC TRANSMISSION  |
| <b>Fuel Type:</b>    |                         |
| <b>Ext. Colour:</b>  | METALLIC SILVER         |
| <b>Int. Colour:</b>  | BLACK                   |
| <b>Doors:</b>        | 4                       |
| <b>Seats:</b>        | 7                       |
| <b>Drive Type:</b>   | AWD                     |



### Asset Identification

|                   |                   |               |           |               |  |                       |  |
|-------------------|-------------------|---------------|-----------|---------------|--|-----------------------|--|
| <b>Odometer:</b>  | 94,734kms SHOWING | <b>Rego:</b>  | NO PLATES | <b>State:</b> |  | <b>Expiry:</b>        |  |
| <b>VIN:</b>       | KL3CD2669GB531436 | <b>PIN:</b>   |           |               |  |                       |  |
| <b>Engine No:</b> |                   | <b>Hours:</b> |           |               |  |                       |  |
| <b>Papers:</b>    |                   | <b>Keys:</b>  | 1         | <b>Books:</b> |  | <b>Service Books:</b> |  |

### Features

ABS, AIR BAG, AIR CON, ALLOY WHEELS, BLUETOOTH, CENTRAL LOCKING, CRUISE CONTROL, IMMOBILISER, POWER WINDOWS, ROOF RACKS, SIDE STEP, SPARE WHEEL, SUNROOF, TRACTION CONTROL, REVERSE CAMERA & LCD

KEY #21

### Condition

| Location                  | Damage                    |
|---------------------------|---------------------------|
| RIGHT REAR BUMPER & GUARD | IMPACT DAMAGE & SCRATCHES |
| FRONT RIGHT BUMPER        | SCRATCHES & SCRAPES       |