



CLUB
MARINE
INSURANCE

CONDITION REPORT

TRAILER BOATS / TRAILER SAILERS

Client's Name Haines 540C Policy No. _____
Client's Address _____ Home Ph. _____
Boat Dealer _____ By _____ Signed _____ Date _____

HULL

Make	HIN No.	Year Built	Reg. No.	Construction
Check visual condition of:				
Keel, Strakes and Chines	Good ☒	Poor ☐	Is Hull fitted with:	Yes ☐ No ☒
Rest of Bottom Area	☒		Operative Engine Blower	
Welds	☒		Gas Detector fitted	
Transom	☒		Battery Isolation Switch	
Bow and Upside	☒		Bilge Pump operational	
Deck/Cabin	☒		Are all Deck fittings secure	
Windscreen	☒		Navigational lights operational	
Steering System	☒			
Canopy/Storm Cover	☒			
Osmosis present	Yes ☐ No ☒			

Please note your general comments on the overall condition of the hull, specifically those items that require immediate attention:

Fuel tank needs a repair

MOTOR

Port:	Make	Year Built	Serial No.	HP
S/Board:	Make	Year Built	Serial No.	HP
Visual check for:	Yes ☐ No ☒		In or out of Test Tank, check:	Yes ☒ No ☐
Visible Damage			Choke	
Loose Parts			Alternator Charging	
Corroded/Deteriorated Parts			All Instruments Functioning	
Fuel Storage:	Yes ☒ No ☐		Water Pressure Gauge	
Inbuilt Tanks	☒		(check only in Test Tank)	
Vented	☒		Cooling System Functioning	
Deck Filled	☒		Water Leaks	
Earthed	☒		Fuel Leaks	
Portable Type	☒			Good ☒ Poor ☐
Safely Secured	☒		Throttle Operation	
Check condition of:	Yes ☒ No ☐		Starting System	
Fuel Lines, Filters and Connections			Run Motor (check water flow)	
(meet Industry Standards)			Motor Idle (out of gear) atrpm	
Check condition/operation of:	Good ☒ Poor ☐		Motor Idle (in gear) atrpm	
Engine Oil	☒		Motor operated under load	
Tilt/Trim System	☒		Remove Spark Plugs and check	
Check condition of:	Good ☒ Poor ☐		Gearshift Operation	
Battery	☒		Condition of Oil	
Electrical System	☒			

Please note your general comments on the overall condition of the motor, specifically those items that require immediate attention: