



**CLUB
MARINE
INSURANCE**

CONDITION REPORT

TRAILER BOATS / TRAILER SAILERS

Client's Name Cruise Craft 600 BR Policy No. _____
 Client's Address _____ Home Ph. _____
 Boat Dealer _____ By _____ Signed _____ Date _____

HULL

Make	HIN No.	Year Built	Reg. No.	Construction
Check visual condition of:				
Keel, Strakes and Chines	Good	Poor	Is Hull fitted with:	Yes No
Rest of Bottom Area	/		Operative Engine Blower	/
Welds	/		Gas Detector fitted	/
Transom	/		Battery Isolation Switch	/
Bow and Upside	/		Bilge Pump operational	/
Deck/Cabin	/		Are all Deck fittings secure	/
Windscreen	/		Navigational lights operational	/
Steering System	/			
Canopy/Storm Cover	/			
Osmosis present	Yes No			

Please note your general comments on the overall condition of the hull, specifically those items that require immediate attention:

A few scratches on bow

MOTOR

Port:	Make	Year Built	Serial No.	HP
S/Board:	Make	Year Built	Serial No.	HP
Visual check for:	Yes No		In or out of test tank, check:	Yes No
Visible Damage	/		Choke	/
Loose Parts	/		Alternator Charging	/
Corroded/Deteriorated Parts	/		All Instruments Functioning	/
Fuel Storage:	Yes No		Water Pressure Gauge	/
Inbuilt Tanks	/		(check only in test tank)	/
Vented	/		Cooling System Functioning	/
Deck Filled	/		Water Leaks	/
Earthed	/		Fuel Leaks	/
Portable Type	/			Good Poor
Safely Secured	/		Throttle Operation	/
Check condition of:	Yes No		Starting System	/
Fuel Lines, Filters and Connections	/		Run Motor (check water flow)	/
(meet Industry Standards)	/		Motor Idle (out of gear) at rpm	/
Check condition/operation of:	Good Poor		Motor Idle (in gear) at rpm	/
Engine Oil	/		Motor operated under load	/
Tilt/Trim System	/		Remove Spark Plugs and check	/
Check condition of:	Good Poor		Gearshift Operation	/
Battery	/		Condition of Oil	/
Electrical System	/			

Please note your general comments on the overall condition of the motor, specifically those items that require immediate attention:

Motor runs well