



CONDITION REPORT

TRAILER BOATS / TRAILER SAILERS

Client's Name Southwind 640 Policy No. _____
Home Ph. _____

Client's Address _____

Boat Dealer _____ By _____ Signed _____ Date _____

HULL					
Make	HIN No.	Year Built	Reg. No.	Construction	
Check visual condition of:	Good	Poor	Is Hull fitted with:	Yes	No
Keel, Strakes and Chines	/	/	Operative Engine Blower	/	/
Rest of Bottom Area	/	/	Gas Detector fitted	/	/
Welds	/	/	Battery Isolation Switch	/	/
Transom	/	/	Bilge Pump operational	/	/
Bow and Upside	/	/	Are all Deck fittings secure	/	/
Deck/ Cabin	/	/	Navigational lights operational	/	/
Windscreen	/	/			
Steering System	/	/			
Canopy/Storm Cover	/	/			
Osmosis present	Yes	No			

Please note your general comments on the overall condition of the hull, specifically those items that require immediate attention:

Hull presents well

MOTOR					
Port:	Make	Year Built	Serial No.	HP	
S/Board:	Make	Year Built	Serial No.	HP	
Visual check for:	Yes	No	In or out of test tank, check:	Yes	No
Visible Damage	/	/	Choke	/	/
Loose Parts	/	/	Alternator Charging	/	/
Corroded/Deteriorated Parts	/	/	All Instruments Functioning	/	/
Fuel Storage:	Yes	No	Water Pressure Gauge	/	/
Inbuilt Tanks	/	/	(check only in Test Tank)	/	/
Vented	/	/	Cooling System Functioning	/	/
Deck Filled	/	/	Water Leaks	/	/
Parted	/	/	Fuel Leaks	/	/
Portable Type	/	/	Throttle Operation	Good	Poor
Safely Secured	/	/	Starting System	/	/
Check condition of:	Yes	No	Run Motor (check water flow)	/	/
Fuel Lines, Filters and Connections	/	/	Motor Idle (out of gear) at ... rpm	/	/
(meet Industry Standards)	/	/	Motor Idle (in gear) at ... rpm	/	/
Check condition/operation of:	Good	Poor	Motor operated under load	/	/
Engine Oil	/	/	Remove Spark Plugs and check	/	/
Tilt/Trim System	/	/	Gearshift Operation	/	/
Check condition of:	Good	Poor	Condition of Oil	/	/
Battery	/	/			
Electrical System	/	/			

Please note your general comments on the overall condition of the motor, specifically those items that require immediate attention:

Motor presents well