

PLEASE LEAVE IN THE VEHICLE



93008105

74

BHPB LV NUMBER LV 005 Rego XII 648 Date 25-11-14

UHF Removed ☒ Reflective Tape / BHPB Logo Removed ☒ Seat Covers Removed ☒ Dune Pole / Beacon Removed ☒

Safety Inspection Completed ☒

Test Drive		P	F	Brake Measurements	
1	Wheel Alignment / Pulling			Disc Rotor	Min. Act.
2	Engine Performance			RHF	23 24
3	Engine Smoke			LHF	23 24
4	Engine Rattles			RHR	
5	Transmission Performance			LHR	
6	Handbrake			Disc Pad	Left Right
7	Brake Pulsations			Front(mm)	4 4
8	Noise / Rattles			Rear(mm)	
9	Fuel Level <u>Full</u>			Drum	Min. Act.
Light Check / Operation				RHR	297 296
10	Turn / Hazard			LHR	297 296
11	Tail / Park			Shoes	Left Right
12	Brake Lights			Rear(mm)	3 3
13	Low / High Beam			Tyre Depth (T.W.I.)	
14	Interior / Instrument			Front (MM)	Left Right
15	Spot Lights / Work Lights	NA		Rear (MM)	4 5
Interior Inspection				Spare (MM)	7 7
16	Wiper / Washers			Tyre Placard	
17	Heater / A/C Operation			195 R 14	
18	Key / Remote Operation	NA		Actual Tyres Fitted to Vehicle	
19	Dash Vent Operation			195 R 14	
20	CD / Radio Operation			VIN & Vehicle Details match JC	
21	Rear Demister Operation			NA	Yes No
22	Rearview Mirror			Check and Confirm Correct Oil Grade	
23	Power / Man Windows			As per Svc. Book or Castrol Site	
24	Door Checktrap			Grade Req. OK	
25	Spare Wheel / Jack / Tools			Accessories	
26	Interior Trim Condition			72	Accessories Working
Exterior Inspection				73	Accessories Fitted Correctly
27	Windscreen / Glass			Item No. Condition / Recommendation Time	
28	Window Tint			Natty Gearshift	
29	Number Plate Surrounds			General dents	
30	Lights / Lenses			No spot-lights	
31	Door / Body Mouldings				
32	Mag Wheels / Hub Caps				
33	Lock Nuts & Key	NA			
34	Bullbar / Nudge Bar				
35	Electric / Man Aerial				
36	Towbar / Tongue Removal	NA			
37	Interstate Plate removal	NA			
38	Overall Body Condition				
Under Bonnet Inspection					
39	Drivebelt				
40	Drivebelt Pulleys				
41	Timingbelt Replacment				
42	Air Filter				
43	Pollen Filter				
44	Battery Level / Test				
45	Radiator / Coolant Condition				
46	Coolant Over Flow Level				

Tech Signature

[Signature]

Northpoint Fleet Management - 1/459 North East Road Hillcrest SA 5086
 Ducala Pty Ltd A.C.N. 008 031 874 ABN 38 008 031 874 Trading as Northpoint Fleet Management
 PO Box 186 Greenacres SA 5086 EMAIL: fleetmanagement@northpoint.com.au

Service & Safety

1.5