

Other Maintenance

PM50

[illegible]

Minor Service

Major Service

C Inspection

Other maintenance

A		B	C	D	
				PM50	
DATE	NAME	DESCRIPTION		HOURS	KM'S
15/9/12	P Hill	MINOR SERVICE (1037743)		2	✓ 1360569
17/10/12	P Hill	MAJOR SERVICE		5	✓ 1372,720
		change starter motor (1037919)			
8/11/12	P Hill	MINOR SERVICE (1037964)		2	✓ 1379930
30/11/12	P Hill	MAJOR SERVICE (1037965)		2	✓ 1390,397
3/1/13	P Hill	MINOR SERVICE (1037998)		2	✓ 1406,546
4/1/13	P Hill	fix exhaust guard, fit hubcap		5	
		remove radiator bracket and			
		weld up			✓ 1037999
7/1/13	P Hill	fit radiator bracket to		1	
		truck		1	✓ 1038000
19/1/13	P Hill	fit new mudguard to LHF of axle		1 1/2	✓ 1038022
25/1/13	P Hill	MAJOR SERVICE		2	✓ 1410,227
16/2/13	P Hill	MINOR SERVICE (1038056)		2	✓ 1423,454
22-2-13		Cummins Rebuilt Engine (1038300)		1425887	kms.
9/3/13	P Hill	MINOR SERVICE (1038081)		2	✓ 1430,876
4/4/13	P Hill	MAJOR SERVICE (1038097)		2	✓ 1445,461
18/4/13	P Hill	MINOR SERVICE (1038098)		1	✓ 1454,101
6/5/13	P Hill	MAJOR SERVICE (1038171)		2	✓ 1459,819
6/5/13	P Hill	Go to RTA to get defect off (1038299)		2	✓ 1459,819
15/6/13	P Hill	MAJOR SERVICE (1038195)		1 1/2	✓ 1453,526
10/7/13	P Hill	MINOR SERVICE (1038199)		1 1/2	✓ 1491,494
6/8/13	P Hill	MAJOR SERVICE (1038211)		2	✓ 1502,076
22/8/13	P Hill	MINOR SERVICE (1038298)		1 1/2	✓ 1509,530
16/9/13	P Hill	MAJOR SERVICE (1038303)		2	✓ 1522,325
4/10/13	P Hill	MINOR SERVICE (1038422)		2	✓ 1534,540

			Pm 50	
DATE	NAME	DESCRIPTION	HOURS	KM'S
25-6-12	Blue	Fit Flywheel & clutch Refit	6	
		Gearbox		✓ 1037359
26-7-12	Blue	Reassembled box & truck	7	✓ 1037360
27-7-12	Blue	Remove crossmember at rear of cab	4	✓ 1037361
20/7/12	Matt	Put new mud flap on left back of truck	1	✓ 1037371
25-7-12	David	Repair LOWER MIDDLE SECTION (BULL BAR)	3	✓ 1037402
6-8-12	Blue	Minor Service (1037511)	1	✓ 1340,312
6-8-12	David	ASSIST BLUE	1	✓ 1037468
13/8/12	P. Hill	Help change alternator and idler pulley	2	✓ 1037512
13-8-12	Blue	change Alternator & idler	2	✓ 1037513
21/8/12	P. Hill	change drive dooster, adjust clutch and put 20 litres of Hydro oil in truck	2 1/2	✓ 1037569
21-8-12	Blue	Fit new compressor line	3	✓ 1037570
28/8/12	Matt	Full Service and assist		
		rete with tightening mud card		
		Reas. and taking air bag off (1037619)	3	✓ 1352260
29/8/12	P. Hill	Help with service	3	
		Take LHR airbag out to replace		✓ 1037632
30/8/12	P. Hill	Fit new airbag and supply line to bag	2	✓ 1037633
4/9/12	Matt	Fit mud card on back left	2	✓ 1037677

PM 50

DATE	NAME	DESCRIPTION	HOURS	KMs
16/12/11	David	C-Inspection, Fit indicator to front of truck.	4	1035579
16/12/11	David	major service	4	1035575
31/12	David	wash motor		1036037
4-1-12	David	NEW COMPRESSOR 1273662	Kms.	
15-1-12	David	Adjust clutch	1	✓ 1036096
21-1-12	David	REPLACE 1/4 FRONT BOOSTER	2 1/2	✓ 1036131
1-2-12	Blue	Remove gearbox clutch flywheel	6	✓ 1036185
2-2-12	Blue	Fit new input shaft, bearing & cover. Fit new engine mounts	6	✓ 1036186
3-2-12	Blue	Fit flywheel & clutch Repair clutch shaft Refit gearbox	2	✓ 1036187
6-2-12	Blue	Reassembled gearbox fitted new uni & cab mounts	7	✓ 1036188
7-2-12	Blue	minor service	3	1277891
		weld up Radiator support		✓ 1036189
15-2-12	David	REPLACE EXHAUST ELEMENT (MOUNTING)	1 1/2	✓ 1036241
15-2-12	Blue	Adjust clutch	1 1/2	✓ 1036242
7-3-12	David	MAJOR SERVICE (1036404)	2	✓ 1036403
7-3-12	Math	help service	2	✓ 1036405
20-3-12	David	IDENTIFY REAR DECK	2	✓ 1036497
30-3-12	Math	fix motor light on front Right	1	✓ 1036583
10/4/12	David	REPLACED PANARD ROD BUSSES X 2	2	✓ 1036667
10/4/12	Math	assist Dave with minor service	2	✓ 1036668
10-4-12	DAVE	MINOR SERVICE (1036669)	1	✓ 1036672
5/5/12	Phil	MAJOR SERVICE (1036774)	1 1/2	✓ 1036794
5/5/12	Blue	Help with service	1 1/2	✓ 1036775
12/5/12	Blue	Repair service line on R/H D	1	✓ 1036841
15/5/12	Math	Fit new tail light on Back Right hand side and Blinker all new	2	✓ 1036885
24-5-12	David	FIT R/H MUFFLER	3	✓ 1036906
1/6/12	Phil	MINOR SERVICE (1037001)	1 1/2	✓ 1037027
1-6-12	JEAN	NEW FUEL PRIMING Pump (1037082)	2 1/2, 3	✓ 20,527 Kms
20-6-12	Blue	Remove Gearbox & clutch & flywheel	7	✓ 1037307
21-6-12	Blue	Fitted new cross shaft bushes	4	✓ 1037358

PM 50

DATE	NAME	DESCRIPTION	HOURS	KMs
8-6-11	DAVID	STARTER INSTALL ✓	2	1034445
24/6/11	P. Hill	MAJOR SERVICE ✓	2	210,446
2/7/11	Jared	Replace cruise control switch, grease & free up clutch ✓	3	1034610
4-7-11	Blue	Remove bullbar Weld up bar & Refitted, Rewire Rlt headlight ✓	8	1034761
23/7/11	Jared	Adjust clutch ✓	1	1034796
8/8/11	Jared	Minor service ✓	1	1,226,169
4/8/11	P. Hill	Assist with MINOR SERVICE ✓	2	1034936
17-8-11	David	MAJOR Service ✓	2½	1035061
24/8/11	P. Hill	go to tarpeenan and fix air line ✓	2	1035155
30-8-11	Blue	check over truck for broken not work ✓	2	1035185
30-8-11	Jared	Repair pto airline, check bolts on air compressor ✓	2	1035205
5/9/11	P. Hill	MINOR SERVICES ✓ 1035249	4	1,241,559
24/9/11	Jared	Assist with service, adjust clutch ✓	1.5	1035377
24-9-11	David	MAJOR Service WITH JARED ✓	1½	1035378
7/10/11	P. Hill	MINOR SERVICE ✓ 1035506	1½	1,261,155
5-11-11	David	Fit NEW REVERSING BUZZER ✓	1½	1035682
18-11-11	David	Remove power steering BOX & FUEL TANK TO REPAIR LEAK ✓	8½	1035782
21/11-11	David	Refit fuel tank ✓	2½	1035788
22-11-11	David	Refit FUEL TANK & NEW MIGHT CONTROL VALVES L/H HEADLIGHT ✓	5	1035798
5-12-11	David	Refit STEERING BOX - NEW ✓	1½	1035858
6-12-11	David	Clean MOTOR TO FIND OIL LEAK, REPAIR BULLBAR ✓	5	1035859
11-12-11	Jared	Wash, service, Major service, replace lights ✓	8	1035956
15/12/11	Jared	Fit tail light, Fit reverse light ✓	7	1035956
		Fit new mudguard, Fit new mudflap, Fit new hornet spring, check king pins, ✓		1035956

PM 50

DATE	NAME	DESCRIPTION	HOURS	KMS
20.1.11	Jared.	assist with service	3	1033324
27.1.11	Jared	remove axles	2	1033341
28.1.11	blue	remove front diff		
		fit new diff	3	1033333
31/1/11	blue	remove front drive wheels		
		clean bearing / reline RHF	3	1033334
1.2.11	blue	fit new perard rod bushes	9	1033335
1.2.11	rick	mudguards	5	1033326
2.2.11	Jared.	repair washer bottle		
		repair mudguards / repair light	1	1033375
22.11	blue	Finish off diff / reline	6	
		LHD Front / clean bearing on RHD		1033404
4.2.11	pete	change height valves	1	1033394
8.2.11	Jared	minor service	4	1033376
		tighten poles / replace number plate / tighten A/c compressor		
		replace bonnet straps		
24.2.11	Jared	Major Service	4	1033493
1.3.11	Jared	Replace power steering box	5	1033521
2.3.11	Jared.	Rebuild Horton	7	1033575
10-3-11	Blue	Refill hydraulic tank	1	
		tightened up axle basket LHF		1033531
26-3-11		Repair wire on starter	2	1033722
28-3-11	Jared	Repair wing pins	7	1033740
21.3.11	DAVID	INSTALL RUBBER TUBES UNDER WHEELS	2 1/2	1033741
24.3.11	Jared	Replace wing pins both sides	9	
		replace bonnet straps, rotate front wheels		1033742
28.3.11	Jared	C-Inspection	45	
28.3.11	Jared	Minor Service	1	(1876671)
16-4-11	DAVID	REPLACE LFB AXLE GASKET CHECK OTHERS	2 1/2	1033937
30.4.11	Jared	Fit new drag link	1	1034025
18-5-11	DAVID	REPLACED R/H REAR WHEEL SCAL	2	
11-6-11	Jared	Major Service	4	KK0725
13-5-11	Blue	Minor Service	2	KK94251
30/5/11	Jared	jump start, wax motor, hook up.	1	1034316
2/6/11	Jared	Replace starter relay	2	1034340
8/6/11	Jared	Replace starter motor	1 1/2	1034414

pm 50

DATE	NAME	DESCRIPTION	HOURS	KMs
24.8.10	Jared	repair height valve	1 ✓	1032359
24.8.10	Dean	" " " ✓	2	1032360
30.8.10	Jared	repair indicators & tail lights ✓	1	1032361
3.8.10	Jared	repair wiring on tail lights ✓	1 ✓	1032362
6.9.10	Jared	assist pete with airbag ✓	1 ✓	1032363
6.9.10	pete	replace airbag on RHF of drive ✓	2 ✓	1032364
7.9.10	Jared	Major Service (78519)	2	
		replace u-joint front of front diff/tighten yoke.		
		nut/adjust clutch ✓	✓	1032365
16.9.10	Jared	repair lights ✓	1	1032585
22.9.10	pete	adjust clutch/put bolt in cross member ✓	1 3/4	1032588
28.9.10	pete	Major Service (1091715)	2	1032677
5.10.10	pete	fit new tie rod ends to front end. ✓	2	1032678
15.10.10	Jared	minor Service (102045) ✓	2	1032745
20.10.10	pete	fit new clutch brake to truck ✓	2	
21.10.10	Jared.	repair wiring/replace axle seal/replace bonnet/blocks/ weld mudguard poles ✓	2	1032782
				1032783
1.11.10	Jared	major service		
		fix lights ✓	2.	1033088
5.11.10	Jared	fit exhaust bracket ✓	1	1033089
9.11.10	Jared	replace Lights ✓	1	1033090
20.11.10	blue	helped with service ✓	1 1/2	1033091
20.11.10	pete	major Service (129846) ✓	2	1033092
		tighten diff yoke		
3.12.10	pete	fit new rose pint ✓	1	1033093
17.12.10	Jared	minor Service	3	1033151
12.1.11	Jared	fit clutch adjustment lever/adjust clutch ✓	2	1033277
17.1.11	Jared.	change hydraulic fittings ✓	1	1033210
20.1.11	pete	major service ✓	3	1033239

			PM 50	
DATE	NAME	DESCRIPTION	HOURS	KM'S
18/2/10	R Hill	MAJOR SERVICE	2	969,175
17/2/10	R Hill	MINOR SERVICE ✓ 1031254	3	951,945
15/2/10	R Hill	replace wheel seal		
		Tump start truck, disengage	1h	
		batteries to be checked, fit		
		new window winder ✓ 1031255		
3/3/10	R Hill	replace starter motor ✓	3 1/2	1031274
18/3/10	R Hill	MINOR SERVICE ✓ 1031325	1 1/2	973,966
23/3/10	R Hill	MAJOR SERVICE ✓ 1031326	1 1/2	979,722
9.2.10	Bluc	Straighten Bull Bar	1/2 hr	1031335
3.3.10	Bluc	test Drive	1 1/2 hr	1031335
4.3.10	Bluc	fix gear change	7 1/2 hr	1031335
22.3.10	Bluc	fit new exhaust Brake Switch	2 hr	1031336
31.3.10	Dean	haul home to cummins ✓	4 hr	1031616
23.4.10	laurie	webb and repair top engine		
		support ✓	1 1/2 hr	1031617
29.4.10	peter	fit new indicators to bonnet		
		Fuel up and hook up to trailer		
		check lights ✓	3	1031618
6.5.10	Dean	check over ✓	2 1/2	1031617
5.5.10	pete	fix wrecker and turn header trip on ✓	1	1031618
10.5.10	pete	minor service ✓ 1031619	1	991,404 km
1.6.10	pete	adjust clutch ✓	1	1031909
3.6.10	pete	major service ✓ 1031926	2	1012718
20.7.10	Jarrad	repair parker lights ✓	1	1032053
25.6.10	pete	replace mudguard ✓	1	1032054
21.7.10	Jared	repair lights ✓	1 1/2	1032055
26.6.10	pete	Minor Service 1032358 ✓		(1029994
		remove turbo from truck	1 1/2	

PM 50

DATE	NAME	DESCRIPTION	HOURS	KMs
30/6	Burford	replace RHF Drive stub axle	1	
	(this was entered on TR93)!	gasket and wash truck where oil was	✓	1030351
23/7/09	P. Hill	'MINOR' SERVICE	2	850,766
		Replaced Gearbox oil	✓ 10	30447
11/8/09	P. Hill	'MAJOR' SERVICE	2	859,808
			1030576	
14/9/09	P. Hill	Fix drink lights ✓	1/2	1030582
26/9/09	P. Hill	'MINOR' SERVICE ✓	1 1/2	1030639
31/9/09	P. Hill	replace hose on steer booster	1/2	1030640
18/9/09	P. Hill	'MINOR' SERVICE 2 ✓	2 1/2	821,631 ✓
24/9/09	P. Hill	'MAJOR' SERVICE	5	888,912
		Help dean take Horton off and rekit it, put back on	1030	770 ✓
7/10/09	P. Hill	Fit new air bay and replace 2 Left side guards	3 1/2	1030789
14/10/09	G Burford	Replace 3 trade shop rubbers on fuel tanks	1	1030811
14/10/09	P. Hill	'MINOR' SERVICE	4	901,525
		replace mudguard and pole on LHR, new mud flap and sign	✓	1030812
20/10/09	G Burford	Rig up suspension kit ✓	2 ✓	1030857
23/10/09	G Burford	Weld up bracket for RH front Bennett guard / hop	1	
		Blue R+ water tank	✓	1030876
24/10/09	P. Hill	'MINOR' SERVICE 2 (1030901)	2 ✓	909,489
10/11/09	P. Hill	change coolant hose to header tank	2	1030943
17/11/09	P. Hill	'MAJOR' SERVICE 1031003	2	921,260 ✓
3/12/09	P. Hill	adjust brakes on truck and trailers	1/2	1031067
4/12/09	P. Hill	'MINOR' SERVICE 2	2	942,518
			✓	1031068

					Pm 50
DATE	NAME	DESCRIPTION	HOURS	KM'S	
3/1/9	BLUE	Roll brake pedal apart clean up & lubricate.	3		
		Weld up holes in ball bar & polish up			
5/1/9	BLUE	Replace Seat Cover / Fit LAF Indicator	3		
		Replace tank strap on RNFuel tank.			
14/1/09	P. Hill	"MINOR" SERVICE	2	729,323	
		5 litres of oil		740,375	
29-1-09	Blue	"MAJOR" SERVICE	2	740,375	
9-2-09	Blue	Repacked gearbox & clutch & 1 Cylinder	9		
12-2-09	Blue	ReOiled Flywheel clutch & Gears	8		
		Oil & cross shaft bushes			
25/2/9	MAJOR	"C" INSPECTION	2 1/2	756,421	
17-2-9	Johnny	A Service	1 1/2	759,111	
3/3/9	BLUE	"MAJOR SERVICE"	2	762,199	
16/3/9	P. Hill	"MINOR" SERVICE	2	770,633	
16/3/9	Johnny	- " - - " -	2		
27/3/09	P. Hill	"MAJOR" SERVICE	1 1/2	780,516	
17/4/9	BLUE	Minor Service.	3 1/2	791,458	
		Highen up yolk on front diff.			
17/4/9	Blue	Fitted new starter motor & helped with service	4		
20/4/09	P. Hill	Fit new mudguard to left front	6		
		Fit new mudguard pole and 2nd hand guard on rear, take light pole off, and straighten, fit new light and wire in			
8/5/09	P. Hill	"MAJOR" SERVICE (29979)	1 1/2	800,723	
27/5/09	P. Hill	"MINOR" SERVICE (30062)	2	810,892	
9/6/09	Blue	Fitted new starter motor fix up Radiator support bracket & helped with service, fitted PTO controller.	7		(301200)
9/6/09	P. Hill	"MAJOR" SERVICE	1 1/2	819,670	
22/6/09	P. Hill	"MINOR" SERVICE	2 1/2	839,335	
		Replace bonnet latch and drive shockers		30206	
8/7/09	P. Hill	"MAJOR" SERVICE	3	843,512	
			1030	356	

					PM 50
DATE	NAME	DESCRIPTION	HOURS	KM'S	
28/7/07	Mark	- Repair Headlight	✓ 1/2		
30/7/08	P-Hill	"MAJOR" SERVICE	✓ 3	618,747	
1/8/08	Mark	- Help Josh with alternator	✓ 1 1/2		
11/8/08	BLUE	Rt 3.0 litres of hydraulic oil in tank	✓ 1/2		
19/8/08	P-Hill	"MINOR" SERVICE	✓ 1 1/2	635,317	
19/8/08	Blue	fit new exhaust steel supports	✓ 1		
2/9/08	P-Hill	"MAJOR" SERVICE	✓ 2	642,031	
04/9/08	Mark	- Repair headlight & fit new surround	✓ 1/2		
17/9/08	BLUE	help blue do G.C.	✓ 1 1/2		
17/9/08	Blue	Minor Service	✓ 1 1/2	654,866	
18/9/08	BLUE	Replace shockers on front Diff	✓ 2 1/2		
18/9/08	BLUE	Replace Steering UNIT'S	✓ 2 1/2		
20/9/08	BLUE	Change ESOC fitting 2 snap plug	✓ 1		
30/9/08	Mark	- Help Blue with hydro hose and bag up hydro oil.	1.		
7/10/08	P-Hill	"MAJOR" SERVICE	✓ 2	664,731	
15/10/08	Blue	"minor service"	✓ 1	670,491	
27/10/08	BLUE	"MAJOR SERVICE"	✓ 2	680,255	
27/10/08	BLUE	DO RHR wheel seal & brakes / pull RHF wheel apart & replace springs on brake shoes	✓ 3		
10/11/08	BLUE	"Minor Service"	✓ 6	691,698	
		change tank straps on LH fuel tank pull radiator air & replace bushes Refit Radiator	✓		
10/11/08	BLUE	Remove Radiator & replace bushes Replace power steering lines	✓ 9		
29/11/08	P-Hill	"MAJOR" SERVICE	✓ 1 1/2	703,979	
5/12/08	P-Hill	"MINOR" SERVICE	✓ 1 1/2	713,356	
15/12/08	BLUE	"MAJOR SERVICE"	✓ 5 1/2	722,190	
		Replace washer water bottle / fit dampers on the drivers seat / fit new exhaust clamp Jest down from manifold	✓		

				PM 50
DATE	NAME	DESCRIPTION	HOURS	KMS
22.8.7	Burf	"MAJOR" SERVICE ✓	2 1/2	425,496
		Shocks of front diff road 2 B ✓		
		Tighten up ✓		
13.9.7	P. Hill	MINOR SERVICE		
13.9.7	P. Hill	"MINOR" SERVICE ✓	2	441,445
20.9.7	P. Hill	"MAJOR" SERVICE ✓	3	446,689
10.10.7	P. Hill	"MINOR" SERVICE ✓	2	459,696
9/10/07	P. Hill	fix left headlight ✓	1/2	459
10/10/07	P. Hill	fit new shock plate ✓		
		to right side ✓		
31.10.7	P. Hill	"MAJOR" SERVICE ✓	4	470,656
		Fix low beam headlight ✓		
14/11/07	P. Hill	put new tank rubber on ✓	4	
		and check everything on ✓		
		list ✓		
21.11.7	P. Hill	"MINOR" SERVICE ✓	2	481,165
11.12.7	P. Hill	"MAJOR" SERVICE ✓	3	494,318
31.1.8	Burf	"MINOR" SERVICE ✓	1 1/2	503,658
31.1.8	Burf	weld up brackets on bullbar ✓	1 1/2	
		to 4 side skirt ✓		
27.2.8	P. Hill	"MAJOR" SERVICE ✓	2 1/2	515,770
27.2.8	P. Hill	"C" INSPECTION ✓		" "
21.3.8	P. Hill	"MINOR" SERVICE ✓	1 1/2	529,375
1.4.8	P. Hill	"MAJOR" SERVICE ✓	2	533,754
24/4/8	Burf	help peatchill with service ✓	1/2	
24.4.8	P. Hill	"MINOR" SERVICE ✓	1	548,973
2.5.8	P. Hill	"MAJOR" SERVICE ✓	2	554,226
21.5.8	P. Hill	"MINOR" SERVICE ✓	2	564,471
27/5/08	P. Hill	tighten mudguards, adjust steering ✓	1 1/2	
		brakes, replace Hydro cap ✓		
3.6.8	P. Hill	"MAJOR" SERVICE ✓	2	575,639
12/6/08	Mark	fit new seat belt ✓		
		repair indicator ✓	1.	
18/6/08	P. Hill	"MINOR" SERVICE ✓	2 1/2	587,755
30/6/08	P. Hill	"MAJOR" SERVICE ✓	3	597,348
11/7/8	Burf	help with 61C ✓	1	
11/7/08	P. Hill	"MINOR" SERVICE ✓	1 1/2	608,555

DATE	NAME	DESCRIPTION	HOURS	PM 50 KMs
14/4/07	P-Hill	adjust height values. ✓	2	
23.4.7	DLA	"MAJOR" SERVICE ✓	3 1/2	331793
23.4.7	Rick	Fix L' Stake weld New ✓		
		br on top ✓	2	
30.4.07	Ferg.	Replaced, Adjust, test ✓	2	337.319
		Governor valve ✓		
		Fit another governor valve and ✓		
		test, test signal line and ✓		
		find fault. ✓		
7.5.7	DLA	"MINOR" SERVICE ✓	2	341775
16.5.7	DLA	"MAJOR" SERVICE ✓	3	350266
16.5.7	Rick	Grease & adjust Brakes ✓	1	
24/5/07	P-Hill	change Hydra hose on ✓	1 1/2	
		truck ✓		
31.5.7	DLA	"MINOR" SERV ✓	1 1/2	363388
13.6.7	DLA	"MAJOR" SERV ✓	3	374759
26.6.7	DLA	"MINOR" SERVICE ✓	1 1/2	386697
5.7.7		"MAJOR" SERVICE		
5.7.7	DLA	"MINOR" SERVICE ✓	2	396275
5.7.07	Ferg.	Greased, Repair RH Spring Shackles. 2 ✓		
20.7.07	Commins	Rebuilt engine at 404156kms. } Due to high oil consumption. }		
30.7.7	P-Hill	"MAJOR" SERVICE ✓	3	411,156
31/7/07	P-Hill	Help blue with clutch ✓	3/4	
2/8/07	Rick	Help blue fix fitting Xbaroses ✓		
		air lines, grease lines and ✓		
		change starter Motor and ✓		
		fit 1.95025t Pipes and ✓		
		fit a new Mudgard to RL ✓	9	
31.7.7	Blue	Remove gearbox and clutch ✓	9	
2-8-7	Blue	Refitted clutch and gearbox ✓	9	
		Fitted new starter motor ✓		
4-8-7	Blue	Fitted new wheel seal to LHFW ✓	1	
		steer ✓		
		changed diff & gearbox oil ✓		
		to synthetic Next change 800/100 ✓		
13/8/07	P-Hill	check brake lights and reset ✓	1/2	
		circuit breaker ✓		

PM 50

				PM 50
DATE	NAME	DESCRIPTION	HOURS	KMs
31/7/6	DEAN	" MINOR " SERVICE ✓	2	123,033
12/8/6	HARRY	" MAJOR " SERVICE ✓	3 1/2	134,332
30/8/6	Ferg.	" MINOR " SERVICE ✓	1	145,611
12/9/6	DA	" MAJOR " SERVICE ✓	2	149,419
30/9/6	H. Connors	" MINOR " SERVICE ✓	1	170,178
30/9/6	DA	HELP WITH SERVICE ✓	1	
30/9/6	P.Hill	Fit 4x4 lights, fit 2 new lenses ✓	1/2	
12/10/6	DA	" MAJOR " SERVICE ✓	3 1/2	180,618
23/10/6	DA	" MINOR " SERVICE ✓	1	171,013
3/11/6	P.Hill	Fit new weight gauge ✓	1/2	
2/11/6	DA	" MAJOR " SERVICE ✓	3	200,711
10/11/6	P.Hill	change left mirror head ✓	1/2	
		" FILTER XLF 7222 ✓		
12.11.6	DA	" MINOR " SERVICE ✓	1 1/2	211,439
24.11.6	DA	" MAJOR " SERVICE ✓	2	222,240
4.12.06	P.Hill	take intercooler out and clean ✓	3	
		intercooler out put back in ✓		
8.12.6	DA	" MINOR " SERVICE ✓	2	233,849
15.1.7	DA	" MAJOR " SERVICE ✓	2	247,367
25.1.7	DA	" MINOR " SERVICE ✓	2	257,027
3.2.7	DA	" MAJOR " SERVICE ✓	3	267,631
3.2.7	DA	" C " INSPECTION. ✓	3	267,631
8.2.7	DA	REPLACE GOVERNOR VALVE ✓	1	
16.2.7	DA	" MINOR " SERVICE ✓	2	277,067
22.2.7	DA	REPLACE CRUISE SWITCH ✓	2	
1.3.7	DA	" MAJOR " SERVICE ✓	3	289,593
1.3.7	BLUE	REMOVE & REPLACE RECO ALTERNATOR ✓	2	
8.3.07	P.Hill	replace lights and driving light. ✓	2	
10.3.7	Blue	Remove intercooler blow out & refit ✓	2	
		straighten guards to fit Bonnet ✓		
15.3.7	Blue	" MINOR " SERVICE ✓	1 1/2	299,505
28.3.7	DA	" MAJOR " SERVICE ✓	2	310,684
28/3/07	P.Hill	Adjust Height valves ✓	1	
31/3/07	P.Hill	Fit new height valve and test ✓	1 1/2	
21-3-07	Blue	Fit new height valves ✓	1 1/2	
11.4.7.	DA	" MINOR " SERVICE ✓	2	321,192
12.4.7	Rick	check spots Not working properly ✓	1 1/2	
11/4/07	P.Hill	start 2 fit plug, Josh Frying ✓	1/2	