

V18

ISUZU FVR 32

Terra Forma Civil

Year	1999
Make	ISUZU
Model	FVR 32
Plant Type	9t TIPPER
Weight	
Identification No. PIN/VIN	JAL FVR 32HX3000012
Registration No.	WHA 379



Engine Specifications	
Engine displacement	
Number of cylinders	
Cylinder firing order	
Engine Make	Isuzu
Engine No.	895337

Fluid Specifications	Capacity
Engine Oil Type	J-MAX
Fuel Type	
Hydraulic Oil Type	
Transmission Fluid Type	BP EZY SHIFT
Diff	85 / 140

Miscellaneous	
Battery size	
Width, Length & Height	
Tyre Size	
Tyre Pressure	

Part Numbers	Recommended	Equivalent
Air filter Inner	1142151250	P823366
Air filter Outer	1142151830	P82312
Fuel filter	1132400791	
Oil filter	1132401940	
Fan Belt Sizes	8943963754	
Alternator Type / Size		

Year	1999
Make	ISUZU
Model	FVR 32
Plant Type	9t TIPPER
Weight	
ID No. PIN/VIN)	JAL FVR 32HX3000016
Registration No.	WHA 692



Date	Completed by	Description of Work	Done Hrs/KM's
19/08/2006	Beaurepaires	4 retreads	
21/08/2006	Mr Sparky	electric brake kit, phone kit	
8/09/2006	Middleton Auto Electrics	check airconditioning	
11/09/2006	NE Isuzu	hub cap	
27/09/2006	NE Isuzu	repair radio	
28/09/2006	Enzed	hose, clamps, etc	
3/10/2006	NE Isuzu	Thermostat & Gasket	
11/10/2006	Truckline	Mirror	
22/12/2006	Austrahose	Check Valve Swing & Parts	
23/01/2007	NE Isuzu	Radiator Cap	
30/01/2007	NE Isuzu	Climate Trans	
7/02/2007	Adrian Schwab	Bore on selector housing honed & o-rings replaced.	
8/02/2007	Austrahose	50mm Camlock, Galv. & Red Sockets & Hex Plug	
17/02/2007	NE Isuzu	Clutch Replaced	99524.0
30/05/2007	NE Isuzu	Gasket & Hub Cap	
8/08/2007	Adrian Schwab	globe replaced on RH brake light	100600.0
4/09/2007	NE Isuzu	Fuel Cap & Restrictor	
22/01/2008	Baxters	Stop Light Switch	
21/02/2008	NE Isuzu	Oil, Fuel & Air Filter + Climate Trans, Oil Gear & Wiper Refill	
20/10/2008	NE Isuzu	Fender	
27/02/2009	NE Isuzu	R/H Light Lamp	
14/04/2010	SOS	Strip & Puncture Repair	
29/04/2009	Adrian Schwab	10,000 KM Service Done - AS	111264.0
1/05/2009	NE Isuzu	Oil & Fuel Element + Engine Oil + Air Filters	
10/05/2010	Enzed	Black Braided Tube, Hose + Connectors & Clamps	
12/05/2009	Adrian Schwab	Left Hand Rear Booster Replaced - AS	
19/05/2009	NE Isuzu	Brake Chamber	
20/05/2009	SOS	Change Tyre & Fit Spare	
20/05/2010	Salisbury Towbar Service	HeavyDuty Towbar Installed	
2/06/2009	SOS	Repair Puncture	
29/06/2010	NE Isuzu	Elements, Engine Oil, Filters + Coolent	
17/07/2010	Adrian Schwab	10,000km Service Done - AS	120658.0
6/01/2011	Motor Traders	Battery + Joiner	
10/01/1941	Hoist Hydraulics	Catch 30mm	
17/01/2011	NE Isuzu	Mudflap, Cable Ties, 5Pin Large Round Metal + Lamp	
18/01/2011	SOS	Puncture Repair	
2/02/2011	SOS	4 New Tyres	
17/03/2011	SOS	4 New Tyres	
5/12/2011	Direct Automotive	Replace Clutch - Towed in Repaired	
21/02/2012	NE Isuzu	130,000km Service Complete	130635
23/05/2012	Paul Chenoweth	New Flashing Beacon Light Fitted	131298
4/09/2012	NE Isuzu	Damage to Combo Switch - Repaired & Fixed	