

V22

VOLVO TRUCK

Terra Forma Cívil

Year	1994
Make	VOLVO
Model	FL7
Plant Type	Truck
Weight	8380
Identification No. PIN/VIN	YV5F5A4D2PD562041
Registration No.	XFV 795



Engine Specifications	
Engine displacement	
Number of cylinders	6
Cylinder firing order	
Engine Make	VOLVO
Engine No.	TD73ES30461317

Fluid Specifications	Capacity
Engine Oil Type	27 LTS
Fuel Type	DEISEL
Hydraulic Oil Type	
Transmission Fluid Type	
Grease Type / Brand	

Miscellaneous	
Battery size	4 x 6V
Width, Length & Height	
Tyre Size	11R 225 - 148/ 145L
Tyre Pressure	100 KPI

Part Numbers	Recommended	Equivalent
Inner Air	1665886	P780815
Filter Oil	477556	P550425
Fuel filter	2 x 8193858	P553004
Oil filter	466634	P553191
Fan Belt Sizes		
Alternator Type / Size		
Coolant Filter		

Year	1994
Make	VOLVO
Model	FL7
Plant Type	Truck
Weight	8380
ID No. PIN/VIN)	YV5F5A4D2PD562041
Registration No.	XFV 795



Date	Completed by	Description of Work	Done Hrs/KM's
22/04/2005	north east isuzu	installed new master cylinder and adjust clutch	
4/07/2005	regency park	required to pass inspection process	
		new muffler fitted, new taillights fitted, reverse light and beeper	
		fitted, mudflaps to steer tyres fitted,	
1/06/2005	Brendon	new brake relay valve fitted due to air leak	268438
17/06/2005	lm hydraulics	repairs to tailgate locking mechanism	
21/06/2005	lm hydraulics	fit air ram to tailgate	
16/06/2005	beaurepairs	8 new retreads fitted	
		tare weight 9.72t	
6/06/2005	Brendon	new door latch and handle assembly fitted	
9/08/2005	Brendon	service oil,oil filters, grease truck, top up coolant,blow air cleaner	272468
1/11/2005	Brendon	fit new front indicator plugs	
11/11/2005	NE Isuzu	replace turbo, gaskets	277997
9/12/2005	Brendon	service oil,oil filters, grease truck, blow air cleaner,fit new oil	278678
		filter mount, fit new led rear combination lights,	
27/01/2006	Bill Turner	repair radio aerial	
15/02/2006	Bill Turner	adjust brakes, inflate tyres, fit number plate, service Honda pump	
13/02/2006	Mr Sparky	relocate No plate, s&f plate light	
21/03/2006	beaurepairs	fit new tyre	
9/03/2006	NE Isuzu	replace clutch	280026
4/05/2006	Beaurepairs	2 retreads, 1 tyre	218186
26/05/2006	Hitachi	new fan belts	870
20/06/2006	Adrian Schwab	fit U bolts, tighten & weld subframe mounts for tipper body, replace headlight switch, replace grill locks	
24/08/2006	beaurepairs	3 retreads, 1 puncture	
28/08/2006	Independent Components Wh	Additional work to fit Alison automatic transmission	
28/08/2006	Mr Sparky	headlights stay on	
1/09/2006	South Central Trucks	Wheel Clamp	
11/09/2006	CMV Dismantlers	Volvo Bumper Bar	
3/10/2006	North East Paint & Panel	repair & Paint Front Bumper	
20/10/2006	South Central Trucks	Wheel Nut & Clamp	
26/10/2006	Norgren	Valve Knob	
27/10/2006	beaurepairs	Puncture	
7/11/2006	South Central Trucks	Seat Belt	
8/11/2006	beaurepairs	Tyre Fitting	
20/11/2006	NE Isuzu	Clips	
20/11/2006	United Fasteners	Xmas Clips White	
13/12/2006	Motor Traders	Exhaust Clamp	
15/02/2007	Baxters	Head Light Globe - H1 24V 70W	
2 of 4		13759-21	4/07/2013

14/02/2007	Adrian Schwab	250 Hr Service	283661
9/03/2007	Motor Traders	Festoon Packs & 12v Bulbs	
15/03/2007	Motor Traders	AM/FM Radio Cassette Player	
30/03/2007	Truckline	Flasher Unit Electronic 12V	
2/04/2007	Ashdown	LED Resistor	
3/04/2007	beaurepairs	Tyre Fitting	
18/05/2007	beaurepairs	Tyre Repair & Fitting	
22/05/2007	Motor Traders	Battery	
5/06/2007	South Central Trucks	Relay & Fuse	
18/06/2007	Green Welding Specialist	Weld split in tank on truck	
7/08/2007	Baxters	Combination Stoptail Light, Indicator Light & Amber Lamp	
10/10/2007	Hitachi	Fuel Filter Spin-on + Lube Spin-on + Bypass s/on Lube	
23/11/2007	beaurepairs	Fitting Truck with rims	
5/12/2007	Hitachi	Lube Bypass Spin-On + Element Primary	
12/12/2007	Adrian Schwab	Oil leak repaired to back of motor.	
12/12/2007	Adrian Schwab	Water hose repaired	285017
12/12/2007	Adrian Schwab	250hr service done	286000
26/02/2008	Austrahose	65mm Diecast Camlocks	
28/02/2008	United Fasteners	Tap, Bolts, Drills & Screws	
4/03/2008	Austrahose	75mm Superflex Red & Clamp	
7/05/2008	beaurepairs	Tyre Fitting Change Over	
26/05/2008	Austrahose	Clamp & Nut Tails	
28/05/2008	Adrian Schwab	250 Hr Service	
31/05/2008	beaurepairs	Puncture Repair	
2/06/2008	Enzed	Clamp & Hose	
2/06/2008	Hitachi	Tection J-Max, Fuel Filter Spin-on + Hyspin AWH46	
10/06/2008	Truckline	Breather 1 1/2 PushOn	
3/09/2008	HeavyAir	Test, Check & Report on Air Conditioning System	
10/09/2008	Adrian Schwab	Passenger Seat Belt Checked - No Problems	
5/11/2008	Enzed	Cab Lift Hose	
21/01/2009	Adrian Schwab	250 Hr Service	
11/02/2009	NE Isuzu	Check & Regas Air Conditioning System	288262
4/03/2009	Gawler Auto Electrics	Battery	
17/03/2009	beaurepairs	Puncture Repair	
1/04/2009	Adrian Schwab	250 Hr Service	
26/05/2009	South Central Trucks	Fit New King Pins Both Sides, Check & Set Axle Stops, Adjust All Brakes etc...	
26/05/2009	Hancock & Just Wheel Alignment	Wheel Alignment + FitDrag Link End	290241
27/05/2009	South Central Trucks	Starter heater	
2/06/2009	SOS Tyre Service	2 new Tyres + Balancing Compound	
23/06/2009	North East Paint & Panel	Repair R/H Door Glass, Fix Consol, clean cab repair roof etc..	
3/12/2009	Enzed	Clamp Block SS X 4	
17/02/2010	Adrian Schwab	1000 Hr Service Done - AS	2941
30/03/2010	South Central Trucks	Door Lock & Button + Clip & Cover	
9/06/2010	Austrahose	Butterfly Wafer Valve	
16/11/2010	SOS Tyre Service	4 New Retreads /- New clean skin spare	
25/11/2010	Austrahose	2" Galv Elbow M/F 90deg	
13/01/2011	NE Isuzu	Engine Oil	
5/02/2011	Adrian Schwab	250hr service done	3377
7/02/2011	SOS Tyre Service	Puncture Repair	
8/04/2011	Diesel Exhaust Systems	Volvo Lip Ring, Donut 114mm Meduim Wall	
12/08/2011	Hitachi	Element Primary, Lube Bypass Spin-On	
18/08/2011	Staff	Changed Oil & Air Filters, Topped up Engine Oil, Topped up Coolant, Fixed Grease Lines, Fitted new Honda Water Pump, Greased Truck	3660
18/08/2011	Hitachi	Fuel Filter Spin-on + Element Safety	

27/01/2012	South Central Trucks	Major Service - Replace Cracked Windscreen, Rect Air Leaks, replace missing clamp, fix oil leak at power steering box, LH Front Spring Bushes Worn,Fix Brakes & Drums	297305
2/04/2012	Burson Auto Parts	Narva Trailer Lamp Kit	
3/04/2012	SOS Tyre Service	1 Run Out Tyre fitted	
4/04/2012	Burson Auto Parts	Trailer Plug, Heatshrink Tubing,	
24/04/2012	South Central Trucks	Major Repairs - Air Leaks, replace valve on compressor, change over gear & fittings, recitify oil leaks and park brake valve	
8/05/2012	Enzed	New Airbrake Hose	
15/05/2012	SOS Tyre Service	1 Run Out Tyre fitted	