V21

Fan Belt Sizes

Alternator Type / Size

NISSAN Navara

Terra Forma Civil

Year		2005
Make		Nissan
Model		Navara
Plant Type		
Weight		
Identification No. P	PIN/VIN	
Registration No.		XEF 752



Engine Specifications		
Engine displacement		
Number of cylinders		
Cylinder firing order		
Engine Make		
Engine No.		
Fluid Specifications		Capacity
Engine Oil Type		Capacity
Fuel Type	-	
Hydraulic Oil Type		
Transmission Fluid Type		
Grease Type / Brand		
Grease Type / Brand		
Miscellaneous		
Battery size		
Width, Length & Height		
Tyre Size		
Tyre Pressure		
Part Numbers	Recommended	Equivalent
Air filter		
Fuel filter	-	

1/21 Repair Log Terra Forma Civil

Year	2005
Make	Nissan
Model	Navara
Plant Type	UTILITY
Weight	
ID No. PIN/VIN)	
Registration No.	XEF 752



Date	Completed by	Description of Work	Done Hrs/KM's
6/05/2006	Beaurepaires	passenger thrust alignment	29580
8/11/2006	Beaurepaires	4 X Tyres & Wheel Alignment	39627
18/11/2006	Grand Nissan	40,000 Service	40253
12/06/2007	Grand Nissan	50,000 Service	47302
4/12/2007	Tom's Car Wash	Mini Detail	
10/06/2008	Kerry's Automotive Group	70,000km Service	75273
15/07/2008	Ceva Logistics	Freighting Ute from Darwin to Adelaide	77686
22/11/2008	Beaurepaires	2 New Tyres & Wheel Alignment in Geraldton WA	84611
8/07/2009	Adrian Schwab	10,000 Service	88830
9/07/2009	Unley Nissan	Element, Oil Filter O-Ring, Cartridge + Mirror Assy etc	
9/07/2009	Flexiglass	Windoor Handle	
15/12/2009	Salisbury Towbar Service	Fit Frame Mounts & Modify Roof Racks	
18/12/2009	Tom's Car Wash	Mini Detail	
21/12/2009	Unley Nissan	80,000 Service	112538
11/01/2010	SOS Tyre Service	2 New Tyres & Wheel Alignment & Balancing & Rotation	
4/07/2010	Adrian Schwab	10,000km Service Done - AS	123465
15/10/2010	Hitachi	RX Super	
20/10/2010	Adrian Schwab	10,000km Service Done - AS	132848
16/12/2010	Fred Vella Tyre Service	Balancing	
16/12/2010	Light Wheel Alignment	Wheel Alignment	
4/02/2011	Adrian Schwab	10,000km Service Done - AS	144689
9/03/2011	Light Wheel Alignment	Wheel Alignment	148086
12/04/2011	Adrian Schwab	50,000km Service Done - AS	153427
14/04/2011	Unley Nissan	Oil Filter Element, Washer Drain, Cartridge, O-Ring + Assy	
19/06/2011	Panorama Crash Repairs	Paint R/H Rear Pillar, front & rear door frame + brush touch	
1/09/2011	Minecorp	Install Reverse Alarm + UHF Radio + First Aid Kit for Mine Specs	160834.0
7/03/2012	CMI Toyota	170,000km Service Complete	170836.0
4/07/2012	CMI Toyota	180,000km Service Complete	180264.0
	,		