VZ4 ISUZ(J INQR450	ierra Forma Civil
Year Make Model	2005 ISUZU	
Plant Type	NQR450	
Weight		this I I I
Identification No. PIN/VIN	JAAN1R70R37102093	the main section of the local day is a section of the local day is
Registration No.	XGI 247	
Engine Specifications Engine displacement Number of cylinders		
-		
Cylinder firing order Engine Make	Isuzu	
Engine No.	185778	
Fluid Specifications		Capacity
Engine Oil Type	CASTROL J-MAX	12 Lts
Fuel Type		
Hydraulic Oil Type		
Transmission Fluid Type	CASTROL J-MAX	3.5
Grease Type / Brand		
Diff	85/140	3.2

 Miscellaneous

 Battery size

 Width, Length & Height

 Tyre Size

 Tyre Pressure

Part Numbers	Recommended	Equivalent
Air filter	8-94430250-0	
Fuel filter	97714339	
Oil filter	8-97371334-0	
Fan Belt Sizes		
Fan Belt Sizes Alternator Type / Size		

V24 Vehicle Repair Log Ter	ra Forma Civil

Year	2005
Make	ISUZU
Model	NQR450
Plant Type	
Weight	
ID No. PIN/VIN)	JAAN1R70R37102093
Registration No.	XGI 247



Date	Completed by	Description of Work	Done Hrs/KM's
21/11/2005	NE Isuzu	5000 km service	5298
19/01/2006	Mr Sparky	Fit auxiliary batteries	
20/02/2006	Mr Sparky	supply & fit jumpstarting studs, isolating switch	
12/04/2006	Mr Sparky	fit charge equaliser to battery	
12/07/2006	NE Isuzu	150000 service	
9/11/2006	UES	Gas Stay & Worklight Globe	
13/03/2007	NE Isuzu	Oil & Fuel Element & Prem. Perform.	
14/03/2007	Adrian Schwab	10,000 KM Service	28291
15/06/2007	Motor Traders	Fresh 2LTR Pump Pk Lighting	
21/08/2007	Enzed	Hose & Swivel	
5/09/2007	Adrian Schwab	10,000km service done	40746
25/09/2007	NE Isuzu	Drain Plug & Gasket	
7/03/2008	NE Isuzu	Elements, Filters & Engine Oil	
12/03/2008	Adrian Schwab	10000km service done	50948
1/05/2008	NE Isuzu	Left Hand Mirror & Bracket	53798
28/05/2008	Beaurepairs	2 New Steer Tyres Fitted	54959
28/05/2008	Baxters	Red & Black Battery Clamps	
3/06/2008	Beaurepairs	2 Cases Fitting & Balance + Disposals	54845
10/06/2008	Motor Traders	Century Battery Hi-Performance	
30/06/2008	Beaurepairs	Puncture Repair	56503
29/08/2008	Hitachi	Tection J-Max	
29/08/2008	NE Isuzu	Filter, Oil Element + Element Kit	
24/09/2008	Adrian Schwab	10,000 KM Service Done - AS	61615
30/09/2008	Panorama Crash Repairs	Repairs from Insurance Claim	
25/02/2009	Adrian Schwab	10,000 KM Service Done - AS	70475
25/02/2009	NE Isuzu	Fuel & Oil Elements + Filters	
10/06/2009	Adrian Schwab	10,000 KM Service Done - AS	80965
10/06/2009	NE Isuzu	Filters, Elements + Engine Oil	
21/07/2009	SOS Tyre Service	4 New Tyres Fitted	85000
1/08/2009	Panorama Crash Repairs	Repair LH Door & Side Pillar + Paintworks	
20/08/2009	Craig Arthur Pty Ltd	Truck Wash	
9/09/2009	NE Isuzu	Oil & Fuel Element & Engine Oil, Lamp & Rubber Mats	
16/09/2009	Adrian Schwab	10,000 KM Service Done - AS	91751
9/10/2009	Craig Arthur Pty Ltd	Truck Wash	
30/10/2009	Craig Arthur Pty Ltd	Truck Wash	
17/11/2009	Craig Arthur Pty Ltd	Truck Wash	
7/12/2009	NE Isuzu	Oil & Fuel Elements + Engine Oil	
14/12/2009	Adrian Schwab	10,000 KM Service Done - AS	100555
31/12/2009	Craig Arthur Pty Ltd	Truck Wash	
8/02/2010	Baxters	Battery Isolater 12v 100amp	
22/03/2010	Craig Arthur Pty Ltd	Truck Wash	
27/04/2010	Craig Arthur Pty Ltd	Truck Wash	
24/06/2010	Craig Arthur Pty Ltd	Truck Wash	
7/07/2010	Adrian Schwab	10,000km Service + Diff & Gear Box Oil Changed + Coolant	110252

23/08/2010	Baxters	Digital Multimeter	
30/08/2010	Craig Arthur Pty Ltd	Truck Wash	
20/09/2010	NE Isuzu	Cooling Belt + A/C Belt	
6/10/2010	SOS Tyre Service	2 New Tyres + Balancing Compound	114800
11/10/2010	Austrahose SA	Retractable Hose + Reel, Nitto Adaptor & Coupling	
13/10/2010	Craig Arthur Pty Ltd	Truck Wash including under Tray	
24/11/2010	Craig Arthur Pty Ltd	Truck Wash	
21/12/2010	Craig Arthur Pty Ltd	Truck Wash	
3/02/2011	NE Isuzu	Oil Element, Engine Oil + Filter	
8/02/2011	Adrian Schwab	10,000km Service Done - AS	120778
9/02/2011	Green Welding Spec.	Test Oil Cooler for Leaks, Found Crack - Repaired Test OK	
24/02/2011	Craig Arthur Pty Ltd	Truck Wash	
1/04/2011	Cavan Agricultural Agenc.	Vent Lid, Pin Linch + R Clip	
6/04/2011	Austrahose SA	Plastic Foot Valve + Skin Fitting	
8/04/2011	Haughton Honda	Comp Air Element, Filter Outer, Oil Filter, Spark Plug etc	
21/04/2011	Craig Arthur Pty Ltd	Truck Wash	
24/10/2011	Battery World	Century Hi Performance Battery	